





















Tube to Male Pipe

<p>Male Connector</p>  <p>4</p>	<p>Male Connector Bored Through</p>  <p>5</p>
<p>Bulkhead Male Connector</p>  <p>5</p>	<p>Male Adapter</p>  <p>6</p>
<p>Male Elbow</p>  <p>7</p>	<p>Male Branch Tee</p>  <p>8</p>
<p>Male Run Tee</p>  <p>8</p>	<p>Reducer Adapter</p>  <p>17</p>





Tube to Tube Union

<p>Union</p>  <p>12</p>	<p>Bulkhead Union</p>  <p>13</p>
<p>Reducing Union</p>  <p>13</p>	<p>Union Elbow</p>  <p>14</p>
<p>Union Tee</p>  <p>14</p>	<p>Union Cross</p>  <p>15</p>

Tube to Female Pipe

<p>Female Connector</p>  <p>9</p>	<p>Bulkhead Female Connector</p>  <p>9</p>	<p>Female Adapter</p>  <p>10</p>
<p>Female Elbow</p>  <p>11</p>	<p>Female Run Tee</p>  <p>11</p>	<p>Female Branch Tee</p>  <p>12</p>

Tube to Welded Systems

<p>Tube Socket Weld Connector</p>  <p>15</p>	<p>Tube Socket Weld Elbow</p>  <p>15</p>	<p>Male Pipe Weld Connector</p>  <p>16</p>	<p>Male Pipe Weld Elbow</p>  <p>16</p>
---	---	--	---